

Domain	CLOTHING PRODUCTION	Unit ID: 141
Title:	Bundle pieces of cut work	
Level: 2		Credits: 2

Purpose

This unit standard specifies the competencies required to bundles pieces of cut work. It includes the assembling of work piece bundles and dispatching of assembled bundles. This unit standard is intended for those who work in an industrial clothing production environment

Special Notes

1. Entry information
Prerequisite:
 - Unit 130 - *Follow workplace safety procedures in a clothing production environment* or demonstrated equivalent knowledge and skills.
2. To demonstrate competence, at a minimum, evidence is required of assembling work piece bundles and dispatching assembled bundles. These tasks must be performed ensuring correct identification of requirement and finishing of the tasks, correct selection and use of appropriate processes, tools and equipment and completing all work to specification.
3. Assessment evidence may be collected from a real workplace or a simulated real workplace or an appropriate simulated realistic environment in which clothing production operations are carried out.
4. Performance of all elements in this unit standard must comply with all relevant workplace requirements and /or manufacturer’s specifications.
5. Regulations and legislation relevant to this unit standard include the following:
 - Labour Act, No. 6, 1992
 - Occupational Health and Safety Regulations No. 18, 1997
 and all subsequent amendments.

Quality Assurance Requirements

This unit standard and others within this subfield may be awarded by institutions which meet the accreditation requirements set by the Namibia Qualifications Authority and the Namibia Training Authority and which comply with the national assessment and moderation requirements. Details of specific accreditation requirements and the national assessment arrangements are available from the Namibia Qualifications Authority on www.namqa.org and the Namibia Training Authority on www.nta.com.na

Elements and Performance Criteria

Element 1: Assemble pieces of cut work

Performance Criteria

- 1.1 Work pieces are numbered in line with workplace specifications.
- 1.2 Work pieces are sorted according to size and shading.
- 1.3 Bundles are assembled and placed according to workplace requirements.

Element 2: Dispatch assembled bundles

Performance Criteria

- 2.1 Assembled bundles are inspected in line with workplace specifications.
- 2.2 Results of inspection are recorded in line with workplace specifications.
- 2.3 Action is taken to rectify or reject faulty components or incorrect bundling.
- 2.4 Bundles are dispatched to relevant section.

Registration Data

Subfield:	Clothing, Leather and Textiles Manufacturing
Date first registered:	28 September 2006
Date this version registered:	28 September 2006
Anticipated review:	2011
Body responsible for review:	Namibia Training Authority